




Version	Date	Change/additions
02.36.81	Sep, 22th 2021	■ Fixed accelerometers, gyros and magnetometers channels not working in some devices
		External modules
		No changes
02.36.76	Sep, 10th 2021	■ Production needs
02.30.76	3ep, 10til 2021	
		Added RPM max value in data recall best laps page
		■ Fixed accelerometers, gyros and magnetometers channels acquisition
		External modules
		No changes








Version	Date	Change/additions
02.36.34	Jun, 11th 2021	■ Improved GPS switch on procedure to prevent the "GPS ERROR" issue External modules No changes
02.36.18	Apr, 2nd 2021	 Improved GPS inizialization Added 2 and 5 minutes to Auto-Off setup time in menu Fixed bug that could cause half RPM value External modules No changes
02.34.29	Nov, 25th 2020	■ Production requirements External modules No changes
02.32.86	Aug, 21st 2020	 Signalling of expansions/Wi-Fi: the two upper left shiftlights blink blue Fix missing data recall graph External modules No changes
02.32.78	Jul, 10th 2020	■ Fixed RPM issue due to wrong RPM factor handling External modules No changes
02.32.74	Jun, 15th 2020	■ Fixed powerup bug that could cause the system to reset (indicated by red LED blinking slowly) External modules No changes
02.32.72	Jun, 9th 2020	 Japanese language update Improved timing of RS232/K-line communication (it helps with some ECU protocols) Added Hour/Date info from GPS tracks Added reference speed used to calculate odometers External modules No changes







Version	Date	Change/additions
02.32.57	Mar, 17th 2020	■ Minor stability improvements
		External modules
		No changes
02.32.52	Mar, 9th 2020	NOTE: production-only release
		Improved handling of poweroff after fast charge
		External modules
		No changes
02.32.49	Feb, 13th 2020	NOTE: production-only release
		■ Improved battery handling
		 Solved missing timeout on ECU channels for some serial protocol (RS232 and K-Line)
		External modules
		No changes
02.30.10	Jun, 12th 2019	■ Fixed bug locking the device in data recall
		■ AIM CAN network improvements
		External modules
		No changes
02.30.04	May, 2nd 2019	Fixed bug on track auto-learning enabling
		External modules
		No changes
02.30.02	Apr, 19th 2019	■ Improved K-line protocols management
		Added open tracks management Added open tracks management
		 Added manual track creation on device In data recall added min speed in best lap page and in all laps page
		External modules
		No changes







Version	Date	Change/additions
02.26.55	Mar, 14th 2019	■ Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones)
		External modules No changes
02.26.50	Jan, 18th 2019	■ Performance Race Mode: fix wrong units of measurement in data recall page (MPH and ft were shown but values were in km/h and m)
		■ ECU: support Adaptronics and Motec M4 ECU drivers
		External modules
		No changes
02.26.38	Dec, 14th 2018	■ Fixed calculated Perfomance Time
		■ Fixed "+/- Best Time" display visualization
		Added "laptime resume visualization" crossing the finish (it can be disabled by menu option)
		External modules
		No changes
02.26.12	Oct, 30th 2018	■ Support for Can Optical Lap(IRM_42)
		■ CAN network fixes
		■ 100Hz CAN output management
		External modules
		No changes
02.26.06	Oct, 5th 2018	■ Fixed bug on backlight set in OFF mode
		■ Fixed power off for external modules when Solo 2 DL is in charging mode
		Fixed bug on Digital output priority handling
		External module
		25.47 Lambda
02.24.05	Sep, 21st 2018	Custom pages with pressure channels: unit of measure is selectable for each individual channel
		Performance race: fixed missing performance entry in data recall
		Fixed bug in led bar handling with predictive lap time
		External modules
		No changes







Version	Date	Change/additions
02.22.81	Jul, 26th 2018	 Fixed power consumption in low power mode (board REV00) Fixed multiplexed CAN protocols management External modules No changes
02.22.67	Jun, 29th 2018	 Added automatic start data recall at the end of the new test recorded Fixed bug in Predictive time calculation that in some cases, with high speed applications, caused bad behavior Fixed bug in System Info menu in "Hw revision" text display External modules No changes
02.22.65	Jun, 22nd 2018	 Improved suspend/powerup handling Support for board revisions C and E External modules No changes
02.22.58	May, 31st 2018	■ Support of k-line protocols External modules No changes
02.22.52	May, 18th 2018	 Added "All Laps" data recall page and "Speed graph with track" data recall page Added in "Wi-Fi" menu the possibility to choose the Wi-Fi channel to use instead of a random selection at boot Fixed issue that, sometimes, after a shut down of the system, didn't allow to switch on again the Solo 2 DL External modules 25.47 Lambda