

September, 10th 2021

MXS 1.2 Release history

Page 1

Version	Date	Change/additions
02.36.76	Sep, 10th 2021	Fixed digital speed parameters from RS3 configuration setup
		External modules
		02.36.64 GPS09: Improved GPS data synchronization
02.34.29	Nov, 25th 2020	Added GPS09 support
		External modules
		35.65 GPS Module: Fix Masterclock received from master that caused bad values in GPS data timestamp
02.32.81	Jul, 17th 2020	Fixed RPM issue due to wrong RPM factor handling
		External modules
		No changes
02.32.72	May, 22nd 2020	Simulators handling
		Added Hour/Date info from GPS tracks
		Added reference speed used to calculate odometers
		External modules
		No changes
02.32.55	Apr, 23rd 2020	General speed up in transmitting configuration
		Solved missing timeout on ECU channels for some serial protocol (RS232 and K-line) (AB#59)
		Improved track visualization
		Digital channels: bug fix on RPM input capture
		Fixed alarms based on BestDiff time
		External modules
		No changes



September, 10th 2021

MXS 1.2 Release history

Page 2

Version	Date	Change/additions
02.32.12	Feb, 10th 2020	Fixed bug that didn't enable the display page after rear camera visualization
		External modules
		No changes
02.32.09	Oct, 17th 2019	First Release including the new graphic engine which has the following improvements:
		 Faster boot time Boot time independent from the number of configured pages
		 Improvement in font visualization quality
		Resizable fonts
		Colorable icons
		This firmware release is compatible ***ONLY*** with the Race Studio 3 releases starting from the 03.30.00
		External modules
		2.30.16 Shift Light Module: support for the new software release (v03.30.00)
		35.64 GPS Module: improved GPS data synchronization
02.30.12	Jul, 11th 2019	Fixed display visualization when large font is used for GEAR measure
02.30.12	50, 11112019	 Fixed display visualization when large forms used for GLAR measure Fixed bug on Trigger Commands when the action is configured as "Reset Alarms Command"
		External modules
		 40.63 Channel Expansion/TC Hub: no changes for these loggers
		- 40.03 Channel Expansion/ TC Hub. no changes for these loggers
02.30.10	Jun, 12th 2019	Fixed bug locking the device in data recall
		AIM CAN network improvements
		Fixed the calibration of the Expansion channels
		External modules
		40.62 Channel Expansion/TC Hub
		35.61 GPS Module
02.30.06	May, 23rd 2019	Fixed reset gear calculation
		Popup management:
		 Background color configurable from RS3 Txt color configurable from RS3
		External modules
		No changes
		No changes



September, 10th 2021

MXS 1.2 Release history

Version	Date	Change/additions
02.30.02	Apr, 19th 2019	Improved K-line protocols management
		Added open tracks management
		External modules
		No changes
02.26.57	Mar, 22nd 2019	Fix speed indication in miles for analog controls
		External modules
		No changes
02.26.55	Mar, 14th 2019	Improved ADC accuracy
		GPS page skipped when the vehicle is moving
		Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones)
		Fix bug on clear alarm by keypress
		Fix display bug which could lead to device resets with heavy configurations (multiple pages)
		External modules
		No changes
02.26.53	Feb, 14th 2019	Fixed inertial platform orientation
		External modules
		02.26.51 Shift Light Module
		Fixed issues with some ECUs
		No changes for the other modules
02.26.50	Jan, 18th 2019	Digital inputs
		Support for Memory Module, Strada Logger and GS-Dash
		ECU: support Adaptronics and Motec M4 ECU drivers
		ECU: support Adaptronics and Motec M4 ECU drivers External modules
		External modules



September, 10th 2021

MXS 1.2 Release history

Page 4

Version	Date	Change/additions
Version	Date	change/additions
02.26.35	Dec, 5th 2018	Added management of Shift Light Module
		Added the support for auto brightness levels configuration (day brightness level, night brightness level and threshold are now fully configurable)
		External modules
		No changes
02.26.12	Oct, 30th 2018	Support for CAN Optical Lap (IRM_42)
		CAN network fixes
		I00Hz CAN output management
		External modules
		No changes
02.26.08	Oct, 15th 2018	Improved synchronization of GPS data
		External modules
		35.60 GPS Module
		25.47 Lambda
		40.61 Channel Expansion/TC Hub
		70.03 Remote buttons interface
02.26.06	Oct, 5th 2018	Fixed bug on Digital output priority handling
02.26.01	Oct, 1st 2018	Added support for rear cam and rear cam configuration menu
02.20.01	000, 1902010	Fix on units of measure visualization
02.24.04	Sep, 21st 2018	Support for RS232 protocols
02.22.96	Sep, 11th 2018	Fixed potentiometers calibration
		Improved display management when ECU CAN stream has very few fields
02.22.93	Sep, 4th 2018	Support for fuel set/reset using Race Studio 3
		Fix on visualized unit of measure
02.22.81	Jul, 27th 2018	Fixed Remote button interface compatibility
		Fixed multiplexed CAN protocols management