

MyChron5S Release history

Version	Date	Change/additions
02.36.94	Dec, 10th 2021	<ul style="list-style-type: none">▪ Fixed bug on Daylight Saving Time application in Southern Hemisphere▪ Fixed Mychron Expansion channels configuration in recording file: in some cases the channels were missing in RS3 Analysis visualization <p>External modules No changes</p>
02.36.80	Sep, 14th 2021	<ul style="list-style-type: none">▪ Fixed bug that caused no laps tests <p>External modules No changes</p>
02.36.78	Sep, 10th 2021	<ul style="list-style-type: none">▪ Fixed shut down procedure that in some devices didn't working <p>External modules No changes</p>
02.36.55	Jun, 17th 2021	<ul style="list-style-type: none">▪ Improved GPS switch ON procedure to prevent the "GPS ERROR" issue <p>External modules No changes</p>
02.36.32	Apr 27th 2021	<ul style="list-style-type: none">▪ Improved GPS data time synchronization▪ Fixed channels acquisition name that caused issue with Race Studio Analysis mathematical channels <p>External modules No changes</p>
02.36.21	Apr 9th 2021	<ul style="list-style-type: none">▪ Fixed missed system switch on events▪ Fixed bad display reset events <p>External modules No changes</p>

MyChron5S Release history

Version	Date	Change/additions
02.36.19	Apr 2nd 2021	<ul style="list-style-type: none">■ Improved GPS initialization■ Fixed unexpected system cycle of restart when the internal battery is charged and the external battery is connected■ Fixed temperature channels visualization in custom page (sometimes missing, blank value when digits number was greater than 3) <p>External modules</p> <p>No changes</p>
02.34.43	Jan 19th 2021	<ul style="list-style-type: none">■ Fixed temperatures on display visualization when two sensors with the same function are set (e.g. EGT1/EGT2)■ Fixed selected track name visualization on display■ Improved RPM measure calculation■ Improved display management in case of electro-magnetic noise situations <p>External modules</p> <p>No changes</p>
02.34.34	Nov 13th 2020	<ul style="list-style-type: none">■ Fixed bug that could cause half RPM value■ Fixed temperature max/min values in resume lap page and in data recall <p>External modules</p> <p>No changes</p>
02.34.24	Oct 14th 2020	<ul style="list-style-type: none">■ Improved GPS status visualization in GPS track page■ Added missing "Auto" mode in backlight menu■ Added "Rec with GPS speed" in debug mode menu■ Fixed bug on RPM acquisition that caused RPM calculated as half of the true value■ Fixed track autolearning enable/disable in GPS track page■ Fixed alarms menu setup■ Fixed unit measure conversion of temperatures in data recall pages■ Fixed data recall for Oval Race mode <p>External modules</p> <p>No changes</p>